



Aster Hobby Co.,Inc.  
1-13-34 Hakusan , Midori ku,  
Yokohama Japan 2260006  
info@asterhobby.jp  
[http:// www.asterhobby.com](http://www.asterhobby.com)

---

July 7<sup>th</sup>, 2010

## **R5MT KIT    Important Notice**

### **packaging error of the cylinder covers**

Aster Hobby Co.,Inc regrets to inform all the 5MT kit owners that a wrong set of cylinder cover may be packed in your kit.

What you are requested to do

1. Please locate the cylinder covers (12-19 & 20 for green livery 12-21 & 22 for black livery) packaged in the section 12 pouch and check if the supplied covers are correct for the livery you have purchased.

If you are an owner of black kit, please check that the supplied cylinder covers have linings in **red color**, matching the color of the boiler banding and the lining on the valance of the running boards. Please also check that the vertical rivet lines on both sides are positioned **inside** the red linings.

If you are the owner of green kit, please check that the cylinder covers have linings in **orange** color, matching the color on the boiler band and of the lining on the valance of the running boards. Please also check that the vertical rivet lines on both sides are positioned **outside** the orange linings.



The correct cylinder shrouds for black livery (left) and for green livery (right).

2. If above points are not confirmed with the parts you have, please return them to the Aster distributor for replacement. If you have already finished assembling the locomotive, carefully uninstall the running boards and remove the cylinder covers. (You do not have to remove the boiler,

smoke box and the cab.)

It may take time until you receive the correct cylinder cover set. In this case, you are able to proceed with assembly without these cylinder covers. If you do so, please do not yet install 18-23 dummy ejector valve, 19-14 (G) & 15 (B) dummy control valve, and 19-16 dummy valve pipe in section 18 & 19. These detail fittings must be installed after fitting the correct cylinder covers by temporarily removing the running boards.

Aster Hobby Co.,Inc. sincerely apologizes for any inconvenience caused by this matter. We will endeavor to avoid such mistakes in future kits.

Sincerely,  
Aster Hobby Co.,Inc.